

INDUSTRIAL FIELD REPORT


OFFSHORE OIL RIG - LEAKING CIP TANK



BEFORE



AFTER



1 SITUATION

On the oil rig **SOUTH ARNE** in the Danish North sea, they were experiencing a constant loss of fluids in their CIP Tank (clean in place tank). The fiberglass tank didn't have the right structural support, resulting in cracks in the joints of walls and floor.

2 SOLUTION

LINE-X® XS350 was sprayed 2.5 mm (1/8 inch) thick onto the fiberglass with tenacious adhesion.

3 AFTER APPLICATION

The coating of LINE-X was completed in 2 hours and back in service soon after with no change in daily operations.

INDUSTRIAL CUSTOMER
Amerada Hess ApS

LOCATION
Offshore Oil rig **SOUTH ARNE** in the Danish North sea.

APPLICATOR
LINE-X Protective Coatings
Denmark A/S
(+45) 39 30 33 88 |
kasper@line-x.dk

FORMULATION
LINE-X® XS350 100% solids
polyurea sprayed on lining

APPLICATION SYSTEM
GRACO E-XP2
with Fusion Gun.

For more information on LINE-X Industrial Coatings Division, please contact:

6 Hutton Centre Drive, Suite 500, Santa Ana, California USA 92707 | (800) 831-3232 (Office) | www.line-xicd.com

